





Google Aerial



Excerpt from NOAA Nautical Chart #12324



Inspection Limits, Baseline, & Sheet Pile Pair Numbering with NJDEP 2015 Aerial

PHOTOS



Photo 1: High Bar Harbor Yacht Club



Photo 2: Overall view of northern section of new wave screen



Photo 9: View of bulkhead east of C Dock



Photo 10: Wale that is east of C dock with heart rot



Photo 13: Deterioration of sheet piles and wales west of B Dock



Photo 14: Close up of Photo 13 showing incipient holes in sheet pile and holes/heart rot in middle wale



Photo 15: View of the northwest corner of the bulkhead



Photo 16: Typical safety ladder and view of the portion of bulkhead in the tidal zone



Photo 17: Deteriorated bulkhead with hole in sheet pile at north side near the northwest corner



Photo 18: Looking south along the bulkhead and pool deck with subsided walkway



Photo 24: Plywood patches on bulkhead near the south end of G Dock



Photo 25: View of the south bulkhead return



Photo 26: Looking south along the bulkhead and club house deck



Photo 27: Wale with 70% section loss and hole in sheet pile near slip F Dock Slip 6